海迈电缆
Himake Cable
Kevlar
Buffer
Coating
Optical Fiber
Outer Jacket
www.himakecable.com
info@himakecable.com

□□□□□

1 □□□□ □□□□□□□□□□□□□□□□□□□□□□□□□ 2
2. □□□□□□□□□□□□□□□□□
3. □□□□□□□□□□□□□□□□□□□□

□□ Φ	□□□□ □□□□□ φ	□□	□□ □□□□□□ (N)		□□ □□□□□□□□□ N (100 m)		□□ □□□□ (mm)	
(mm)	(mm)	(kg/km)	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□
1.6x3.4	0.6	4.80	150	80	500	100	30%	10 D
1.8x3.8	0.6	5.00	150	80	500	100	30%	10 D
2.0x4.2	0.9	7.00	150	80	500	100	30%	10 D
2.4x5.0	0.9	9.00	150	80	500	100	30%	10 D
2.8x5.8	0.9	11.50	150	80	500	100	30%	10 D
3.0x6.2	0.9	12.50	150	80	500	100	30%	10 D

(□□□)

□□ Φ	□□□□ □□□□□ φ	□□	□□ □□□□□□ (N)		□□ □□□□□□□□□ N (100 m)		□□ □□□□ (mm)	
(mm)	(mm)	(kg/km)	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□
2.0x4.2	0.60	31	1000	300	1000	500	30%	10 D
2.4x5.0	0.60	32	1000	300	1000	500	30%	10 D
2.8x5.8	0.60	35	1000	300	1000	500	30%	10 D
3.0x6.2	0.60	36	1000	300	1000	500	30%	10 D

□□□□□

1. □□□□□□□□□

Brand new material

> Smooth

> Anti-UV

> Long-life

High Quality Fiber

> Fast

> Long and stability transmission

> Low Attenuation.

High Quality PBT Loose Tube Material

> Anti-aging

> Good Protection

info@himakecable.com

ADVANCED PRODUCTION EQUIPMENT

Advanced Production Equipments can guarantee qualified product.

Optic Fiber Cable Testing

- Fiber Testing
- Testing after fiber coloring
- Testing after fiber stranding
- Testing after fiber optic cable jacketing

APPLICATION

✔ Pipeline

✔ Overhead

✔ Direct bury

Packaging & Shipping

PACKING AND SHIPPING

- Each single length of cable shall be reeled on wooden Drum suitable for long-distance shipment.

info@himakecable.com