□□□□□

1 □□□□ □□□□□□□□□□□□□□□□□□□□□□□ 2
2 □□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□ □□
3. □□□□□□□: □□□□□□□□□LSZH□OFNP□PU

□□□□□□□□□□

□□

□□□□□□□□ (□□□□□□□□□□□□□□□□□□□□□□□□□□: info@himakecable.com)

□□ Φ	□□ □□□□	□□	□□ □□□□□□ (N)		□□ □□□□□□□□□ (N\/100 mm)		□□ □□□□ (mm)	
(mm)	(mm)	(kg\/km)	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□
3.0x5.0	1.8	56	800	300	1000	500	30%	10 D
3.2x5.6	2.0	68	800	300	1000	500	30%	10 D
4.0x7.2	2.8	87	800	300	1000	500	30%	10 D

(□□□)

□□ Φ	□□ □□□□	□□	□□ □□□□□□ (N)		□□ □□□□□□□□□ (N\/100 mm)		Min.Bending □□ (mm)	
(mm)	(mm)	(kg\/km)	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□	□□ □□
3.0x5.0	2.0	34	1000	300	1000	500	30%	10 D
4.0x7.0	2.8	42	1000	300	1000	500	30%	10 D

□□□□□

1. □□

Brand new material

> Smooth

> Anti-UV

> Long-life

High Quality Fiber

> Fast

> Long and stability transmission

> Low Attenuation.

High Quality PBT Loose Tube Material

> Anti-aging

> Good Protection

info@himakecable.com

ADVANCED PRODUCTION EQUIPMENT

Advanced Production Equipments can guarantee qualified product.

Optic Fiber Cable Testing

- Fiber Testing
- Testing after fiber coloring
- Testing after fiber stranding
- Testing after fiber optic cable jacketing

APPLICATION

✔ Pipeline

✔ Overhead

✔ Direct bury

Packaging & Shipping

PACKING AND SHIPPING

- Each single length of cable shall be reeled on wooden Drum suitable for long-distance shipment.

info@himakecable.com