

[illegible]

00 000000: (000000000000000000000000: info@himakecable.com)

0000000000 (mm ² 0	00	00000 (mm)	0000	0000
			(000000)	mm)
2c x 1.0 + e	0000000000	1/1.13	90	7.5
3c x 1.0 + e	0000000000	1/1.13	110	8.0
4c 0x 1.0 + e	0000000000	1/1.13	135	8.8
7c x 1.0 + e	0000000000	1/1.13	170	10.5
12c 0x 1.0 + e	0000000000	1/1.13	270	13.7
2c x 1.5 + e	0000000000	1/1.38	110	8.0
3c x 1.5 + e	0000000000	1/1.38	130	8.4
4c x 1.5 + e	0000000000	1/1.38	160	9.5
7c x 1.5 + e	0000000000	1/1.38	230	11.3
2c x 2.5 + e	0000000000	1/1.78	160	9.0
3c x 2.5 + e	0000000000	1/1.78	200	10.5
4c x 2.5 + e	0000000000	1/1.78	250	11.7
2c x 4.0 + e	0000000000	7/0.85	260	11.3
3c x 4.0 + e	0000000000	7/0.85	315	12.1
4c 0x 4.0 + e	0000000000	7/0.85	380	13.3

Quality Comparison

Purity of copper



Excellent

99.93% Oxygen Free Copper ,
Bright color with long life time .



Inferior

Copper including a lot of impurity
Easy heat, short life Easily cause fire

Flame Test



Excellent

No spread , and release a little
white smoke



Inferior

Keep burning , and pop a lot of black
HCL toxic smoke

Resistance Test



Excellent


low resistivity, high conductivity



Inferior

High resistivity, High consumption .
Easy to burning .

Eccentricity Ratio



Excellent

Insulation thickness uniformity



Inferior

Insulation thickness nonuniform
Easy electric leakage fire disaster,

High Pressure Test



Excellent

Jacket no any damage



Inferior

Jacket damaged , reveal conductor

High Temperature Test



Excellent

Jacket no any damage



Inferior

Jacket damaged , reveal conductor

Low Temperature Test



Excellent

Jacket no any damage



Inferior

Jacket damaged , reveal conductor

